

# Download Service Manual Passat B6

Water ingress in the VW Passat 2001 on and Audi A4 and A6 from 2000 on are commonly caused by blocked vents (2 of them, one under the battery and 1 under the front wiper motor) which then allow the compartment between the engine and the windscreen to fill with water, which then leaks into the car and manifests itself as wet carpets in the cabin and boot. Ross-Tech, LLC 881 Sumneytown Pike Lansdale PA 19446, USA Tel: +1 267 638 2300 Fax: +1 215 893 3816 Audi Technical Articles Welcome to our Audi technical articles section. We've gathered a vast collection of useful articles to help you repair many items on your Audi. Techtonics Tuning OEM & Performance Parts for the 1975-1993 Mk1 Water-cooled Volkswagen. Techtonics VW Volkswagen Volkswagon Mk1 Mark 1 I A1 Rabbit Scirocco Jetta GTI ...