

Download Hyundai Accent Electrical

Hyundai Accent 2003 4 door sedan/4 cylinder 130000 miles Engine Electronic control unit ECU Fuses 10 amp ecu fuse located in engine compartment blows within minutes of it being replaced causing high idle & cooling fans not to function. From fuses to motors, relays to complete instrument clusters, we have the replacement electrical parts to maintain driving enjoyment in your Hyundai Accent. Hyundai Accent owners have reported 58 problems related to electrical system (under the electrical system category). The most recently reported issues are listed below. Also please check out the statistics and reliability analysis of Hyundai Accent based on all problems reported for the Accent. Hyundai Accent clock, radio and side mirrors not working.