

Download Mercury Mariner Optimax 200 225 Dfi Outboard Repair Manual Improved

View and Download Mercury Optimax 115 service manual online. Direct Fuel Injection. Optimax 115 Outboard Motor pdf manual download. Also for: Optimax 135, Optimax 150, Optimax 175. That is the No Oil warning. It should not be ignored. It is entirely possible that the alarm module itself has become defective and is sounding the alarm even though the motor is getting oil, but you need to deduce if this is the case before using the motor again.